

Iron and steel

Applications:

Cutting tools, pressure vessels, bolts, hammers, gears, cutlery, jet engine parts, car bodies, screws, concrete reinforcement, 'tin' cans, bridges...

Why?

- Ore is cheap and abundant
- Processing techniques are economical (extraction, refining, alloying, fabrication)
- High strength
- Very versatile metallurgy – a wide range of mechanical and physical properties can be achieved, and these can be tailored to the application

Disadvantages:


- **Low corrosion resistance (use e.g. titanium, brass instead)**
- **High density: 7.9 g cm^{-3} (use e.g. aluminium, magnesium instead)**
- **High temperature strength could be better (use nickel instead)**



Basic distinction between ferrous and non-ferrous alloys:

- **Ferrous metals are 'all-purpose' alloys**
- **Non-ferrous metals used for niche applications, where properties of ferrous metals are inadequate**


Classification of ferrous alloys



Steel metallurgy

Iron is allotropic / polymorphic i.e. exhibits different crystal structures at different temperatures

Most importantly: bcc \leftrightarrow fcc transformation at 912 °C (for pure iron)




Solubility of carbon in ferrite (α -iron, bcc): 0.02 wt%

austenite (γ -iron, fcc): 2.1 wt%


What happens to carbon when crystal structure transforms from fcc to bcc?




Fundamental issue in metallurgy of low alloy steels



Fe 0.4wt% C



Ferrite



**Ferrite + cementite
(Pearlite)**


Also see


**<http://www-g.eng.cam.ac.uk/mmq/teaching/typd/index.html>
and Callister 9.18 for good descriptions of the evolution of
steel microstructure during cooling**


Pearlite

NB Pearlite is a **MIXTURE** of phases (on a very fine scale)


Alternating layers of ferrite and cementite formed simultaneously from the remaining austenite when temperature reaches 723 °C








Fe 1.3 wt% C: Cementite precipitates at austenite grain boundaries, remaining austenite is transformed into pearlite






Mechanical properties

Ferrite: soft and ductile

Cementite: hard and brittle



What happens during rapid cooling?


- Phase diagrams only show stable phases that are formed during slow cooling
- If cooling is rapid, the phase diagram becomes invalid and metastable phases may form
- In the case of steel, the formation of ferrite and cementite requires the diffusion of carbon out of the ferrite phase. What happens if cooling is too rapid to allow this?



The crystal lattice tries to switch from fcc (austenite) to bcc (ferrite). Excess carbon → distorted body-centred lattice → MARTENSITE

Martensite (α')

- Distorted bcc lattice
- Non-equilibrium carbon content
- Forms plate-like or needle-shaped grains




Fe, C 2, Mn 0.7 (wt%)

Martensite

- Hard and brittle
- Applications: crankshafts, spanners, high-tension bolts
- In general too brittle to be useful, BUT if tempered can be used to produce optimum steel microstructure

Tempering

- Heat treatment of martensite carried out at 200-600 °C → allows C atoms to diffuse out of martensite
- Result:



- Fe₃C present as uniform distribution of fine, round precipitates → high strength and toughness



QUENCHED AND TEMPERED steels

Producing quenched and tempered steels


- **Critical cooling rate for martensite formation depends on concentration of alloying elements (e.g. C, Mn, Cr, Ni). Alloying elements delay the formation of ferrite and pearlite → increase chances for martensite formation**
- **Critical cooling rate defines concept of HARDENABILITY (i.e. ease of martensite formation)**
- **Component thickness is an important parameter**
 - ❑ **Medium carbon steels generally used in quenched and tempered condition, high-carbon steels almost always:**
Applications: chisels, hammers, drills, cutting tools, springs...
 - ❑ **Quenching and tempering not possible for low carbon steels → microstructure = ferrite + pearlite**
Applications: car panels, bridges, pipes...

Stainless steels

- **Definition: > 11 wt% Cr. Ni, Mn may also be present**
- **Cr → adherent Cr_2O_3 film → protection against corrosion and oxidation**
- **Most stainless steels are austenitic (alloying elements stabilise γ phase down to room T)**
- **Austenitic stainless steel is non-magnetic → useful as quick test**
- **Ferritic and martensitic stainless steels also available → increases range of mechanical properties available for specific applications (Corrosion resistance not as good as for austenitic stainless steel)**

Cast Iron

High carbon content \rightarrow low melting point



Cast Iron

- Cheap
- Low m.p. → can produce complex parts quickly and easily through sand casting
- BUT brittle

Two types:

- Grey iron: Fe + C (graphite)
Formation of graphite rather than cementite promoted through high C and Si content, slow solidification rate
- White iron: Fe + Fe₃C

Grey cast iron

- Among least expensive metallic materials
- High fluidity → can cast complex shapes
- Graphite flakes → high damping capacity and good machineability → used e.g. as base structure for machines and heavy equipment
- BUT brittle due to shape of graphite flakes → nodular iron better




Fe, C 3.52, Si 3.26, Mn 0.47 (wt%)

RF Cochrane, University of Leeds

© DoITPoMS micrograph library, University of Cambridge

Ductile / Nodular cast iron

- **Addition of Mg / Ce to grey iron → graphite forms as spheres rather than flakes → improved toughness**
- **Applications: valves, pump bodies, gears, crankshafts**



Fe, C 3.2, Si 2.5, Mg 0.05 (wt%)

White cast iron

- **Exceptionally hard, but brittle and almost impossible to machine → used in very few applications e.g. rollers in rolling mills**
- **Used as intermediary in production of *malleable iron*: heat treatment at 800-900 °C causes decomposition of cementite → graphite clusters. Resulting microstructure and properties similar to nodular iron. Typical applications: connecting rods, transmission gears, pipe fittings, flanges**