


***Phase
transformation
heat treatment**


Rate of transformation

Most phase transformations involve a change in composition \Rightarrow **redistribution via diffusion** phase transformation involves:

- **Nucleation** - formation of small particles (nuclei) of the new phase. Often formed at grain boundaries.
- **Growth** of new phase at the expense of the original phase.



* Rate of Phase Transformation



By convention $rate = 1 / t_{0.5}$

The rate of transformation and the time required for the transformation (say 50%) is inversely proportional to one another.

- Rate of transformation : $r \equiv 1 / t_{0.5}$
- $t_{0.5}$ is time required for half way to completion.

Rate of phase transformations

Rate = Reciprocal of time halfway to completion:


$$r = 1 / t_{0.5}$$

Arrhenius equation: thermally activated processes:

$$r = A \exp(-Q_A/kT) = A \exp(-Q_m/RT)$$

↑
Per atom

↑
Per mole



Percent recrystallization of pure copper at different T

Phase transformation

- Phase transformation – Formation of a new phase having a distinct physical/chemical character and/or a different structure than the parent phase.
- It involves two phenomena – Nucleation and Growth
- Nucleation – formation of a nucleus or tiny particles of the new phase.
- A nucleus is formed when the Gibbs free energy, G , of the system decreases i.e. G becomes negative.
- Two types of nucleation – Heterogeneous and Homogeneous
- Growth – Increase in size of the nucleus at the expense of the parent phase.

Metastable versus Equilibrium states

Phase transformation is a time-dependent process, long time is required to reach equilibrium stage.

- Speed or rate of cooling is designed to produce specific microstructure which the phase may not be the **equilibrium one** \longrightarrow **metastable phase**.
- Supercooling or superheating happens very often in practical purpose.

Microstructure and Property Changes in Fe-C Alloys Isothermal Transformation Diagrams

- Eutectoid reaction, at 727°C
- $\gamma \longrightarrow$ pearlite ($\alpha + \text{Fe}_3\text{C}$)
- The lower the temperature, the faster the phase transforms.


From the Isothermal Transformation Diagrams

See Fig. above which is called isothermal transformation diagram.

(Time-temperature-transformation, T-T-T plot)


- **$T \sim < 727^{\circ}\text{C}$ (slightly lower):**
- Phase transformation needs longer time
- Microstructure becomes coarse pearlite.
- **$T \ll 727^{\circ}\text{C}$ (much lower):**
- Phase transformation is quick.
- Microstructure is fine pearlite.

Transforming one phase into another takes time.





How does the rate of transformation depend on time and temperature?

Isothermal Transformation Diagrams



Cooling curve ABCD in T-T-T plot for eutectoid reaction






Fe-Cementite diagram

Eutectic
 $L \rightarrow \gamma + Fe_3C$

Peritectic
 $L + \delta \rightarrow \gamma$

Eutectoid
 $\gamma \rightarrow \alpha + Fe_3C$



Phase transformation in Fe-C system

➤ Peritectic reaction at 1495 °C



➤ Eutectic reaction at 1146°C

$L (4.3\% \text{ C}) \rightarrow \gamma (2.1 \% \text{ C}) + \text{Fe}_3\text{C} (6.67\% \text{ C})$. The eutectic mixture of austenite (γ) and cementite (Fe_3C) is called *Ledeburite*. Compositions right and left of 4.3% are called hyper and hypoeutectic steels (Cast iron) respectively.

➤ Eutectoid reaction at 727°C

$\gamma (0.8 \% \text{ C}) \rightarrow \alpha (0.025\% \text{ C}) + \text{Fe}_3\text{C} (6.67\% \text{ C})$. The eutectoid mixture of ferrite (α) and cementite (Fe_3C) is called *Pearlite*.

➤ Compositions right and left of 0.8% are called hyper and hypoeutectoid steels respectively.

Different cooling treatments

Eutectoid steel (0.8%C)

M = Martensite

P = Pearlite

